

SIZE CHART

SLEEPWEAR PLUS SIZE BASIC SPEC

TOP	1X		2X		3X	
BUST WIDTH	25		26		27 1/2	
LENGTH FM HPS	27		27 1/2		28 1/4	
WAIST WIDTH	24 1/2		25 1/2		27	
SLV LENGTH FM SHOULDER SM	8 1/4		8 1/2		8 3/4	
SWEEP WIDTH	26		27		28 1/2	
NECK WIDTH	9		9 1/4		9 1/2	

ROBE	1X		2X		3X	
BUST WIDTH	26 1/2		27 1/2		29	
LENGTH FM HPS	39 1/2		40		40 3/4	
SLV LENGTH FM SHOULDER SM	23 1/4		23 1/2		23 3/4	
SWEEP WIDTH	29		30		31 1/2	
NECK WIDTH ON FLAT CLOSED	7 1/2		7 3/4		8	

PANT	1X		2X		3X	
WAIST RELAXED AT TOP	17 1/2		18 1/2		20	
FRONT RISE INCL W/B	14 1/2		15		16 3/4	
BACK RISE INC W/B	17		17 1/2		18 1/4	
HIP WIDTH 7" DN	24 1/2		25 1/2		27	
INSEAM FM CROTCH	29		29		29	

SLV LNGLTH

BUST = Measure at the widest part (apex point in circumference)
LENGTH FM HPS = Measure fm top HPS to btm edge.
WAIST = Measure in circumference.
SWEEP WIDTH @ BTM EDGE OT EDGE
NECK WIDTH SM TO SM = ON Flat measure sm to sm .

